

DOI FY 05 Aviation Mishaps




**5 Aircraft
Accidents**



**9 Incidents
with Potential**





DOI FY 05 Aviation Mishaps




The National Transportation Safety Board

NTSB 831.13 Flow and dissemination of accident or incident information.

(b) ... Parties to the investigation may relay to their respective organizations information necessary for purposes of prevention or remedial action.

... However, no (release of) information... without prior consultation and approval of the NTSB.

This is **PRELIMINARY** information, and is provided for accident prevention purposes only



Talkeetna, AK

April 15, 2005

DeHavilland DHC-2

Beaver
(wheel/ski)

Mission

Passenger and
cargo transport

Damage

Substantial

Injuries

2 minor


Procurement

ARA

NTSB ID

ANC05LA058





Talkeetna, AK

April 15, 2005

Issues

Unnecessary
risk taking


High risk pilot

Maintenance
inspection

Pre-mission
briefing

Wreckage
preservation





Talkeetna, AK

April 15, 2005

After landing on the Ruth Glacier, Denali National Park, the pilot taxied outside of the normal maneuver area to drop cargo in a convenient location.

While taxiing, the aircraft approached and attempted to clear a crevasse.

However, the aircraft sustained substantial damage while attempting to jump the crevasse.

Two NPS passengers received minor injuries.




Ruth Glacier landing area

Normal
parking
area



Normal
landing
area

Normal
takeoff
area




Ruth Glacier landing area


Intended
drop off
point

Tail
started to
slide
downhill

"We've got a
big hole in
front of us"

Approximate
touchdown area
and ground path





Intended
drop off
point

Tail
started to
slide
downhill

Two large
campsite
holes
(5'x5'x5')

A photograph of a glacier crevasse. The crevasse is a deep, narrow crack in the ice, filled with snow and ice debris. The surrounding ice is a light blue-grey color. In the background, there are snow-covered mountains. Annotations include a yellow text box at the top center, a yellow text box above the crevasse, two black arrows pointing from the top box to the crevasse walls, and a dashed line with arrows at the bottom indicating the direction of travel.

Crevasse

Approximately 50 feet

Direction of travel


Crevasse




Nearly invisible
due to the slope



**Damage to wing,
gear, and frame**



**Injury to rear seat
passenger due to lack
of shoulder harness
and FAA authorized
modification to the
front seat.**



NTSB Probable Cause Talkeetna, AK, April 15, 2005




The National Transportation Safety Board

The National Transportation Safety Board determined that the probable cause of this accident was ...

Probable Cause

"The pilot's selection of unsuitable terrain for taxi after landing, which resulted in the collapse of the main landing gear and structural damage to the right wing and forward fuselage. A factor associated with the accident was the rough and uneven terrain."





NBC AMD Observations


Talkeetna, AK, April 15, 2005

Corrective Actions/Options

Issues

- Conduct a more thorough background check to identify high-risk pilots
- Conduct a more thorough maintenance check to identify issues such as seats, that although technically legal, are unnecessarily dangerous






NBC AMD Observations ***Talkeetna, AK, April 15, 2005***

Corrective Actions/Options

Issues

- Improve wreckage preservation after an aircraft accident / incident
- Conduct a more thorough pre-mission briefing to improve communications and reduced risk





Delta Junction, AK

July 6, 2005

Cessna A185F
(wheel)

Mission

Cargo transport

Damage

Substantial

Injuries

N/A

Procurement

Fleet

NTSB ID

ANC05TA106





Delta Junction, AK

July 6, 2005

Issues


Unnecessary
risk taking

Go in light
before you
go in heavy

Pre-use
inspection of
landing areas

Medium risk
syndrome






Delta Junction, AK

July 6, 2005

While ferrying a 55 gallon drum of jet fuel into an unprepared landing strip the aircraft's tail wheel struck the ground approximately 53 feet short of the landing area.

The aircraft became airborne for approximately 75 feet before the main gear touched down on the landing strip. Shortly thereafter the propeller impacted the runway.

The pilot was not injured, but the aircraft received substantial damage.



Last Chance Strip

N64 ° 23' 49"
W144° 16' 48"

2,300' MSL


32/14
1000' x 16'
Gravel

Primarily a one-way
strip due to 2-3 °
upslope (140 °)

The narrow valley
makes going around,
especially at high
gross weight,
impossible

Airstrip is not
maintained

12.7.2005



Final approach at
approximately 100' AGL



12. 7. 2005

Initial tail wheel impact approximately 53'
prior to the cleared area



7. 21. 2005

Rut where right main gear touched down



6. 7. 2005


7. 2005

Area of
propeller
strikes



Area where
right main
gear went
into brush







Brush impacted by
right horizontal
stabilizer

7. 21. 2005

Horizontal Stabilizer (inverted)




Scratch marks on the
underside of right-hand horizontal stabilizer



Wrinkling under a fairing at the inboard end
of the right-hand horizontal stabilizer




Inboard view of the crack rack to the inboard right-hand rib of the horizontal stabilizer




Fuselage damage caused by left horizontal stabilizer
and hidden under a fairing



Interior view of damage to aft tailboom bulkhead





NTSB Probable Cause ***Delta Junction AK, July 6, 2005***




The National Transportation Safety Board

The National Transportation Safety Board determined that the probable cause of this accident was ...

Probable Cause

"The pilot misjudged distance / altitude during the landing touchdown and subsequent undershoot, and his failure to maintain directional control of the airplane during the landing roll, which resulted in an on-ground encounter with high vegetation."





NBC AMD Observations


Delta Junction, AK, July 6, 2005

Corrective Actions/Options

Discussion

- Pre-season inspection of high-risk landing areas --
 - ✓ Thorough, documented inspection using a checklist, with results available for pilot briefings
 - ✓ Conducted by an aviation specialist
 - ✓ Discrepancies repaired or marked depending on risk assessment





NBC AMD Observations

Delta Junction, AK, July 6, 2005

Corrective Actions/Options

Discussion

- Pilots should routinely make a practice approach and landing at low gross weights before taking loads into unfamiliar remote or unprepared landing areas
- Landings at locations where it is impossible to conduct a safe -go-around should not be considered routine





Delta Junction, AK

July 28, 2005

Hughes 500D

Mission

Cadastral Survey

Damage

Substantial

Injuries

N/A


Procurement

Exclusive Use

NTSB ID

ANC05TA111





Delta Junction, AK

July 28, 2005

Issues

Unnecessary
risk taking

Land as soon as
possible after
suspected
damage

Safety training
for ground
personnel

Remote fuel site
monitoring and
maintenance






Delta Junction, AK

July 28, 2005

During a cadastral survey, the pilot of the aircraft struck the top of a Black Spruce tree while attempting an approach into a confined area to pick up two passengers.

All five of the main rotor blades received damage.





Landing Direction

15°-20° Upslope

NOTE:

**MD-500 main rotor
diameter is 26'4"**

**Approximate position
of survey crew**

Impact tree





45'

35'


60'


**Landing
Direction**





Tree Marks





NTSB Probable Cause ***Delta Junction AK, July 28, 2005***




The National Transportation Safety Board

The National Transportation Safety Board determined that the probable cause of this accident was ...

Probable Cause

"The pilot's failure to maintain clearance from trees during the approach to landing, which resulted in the main rotor blades striking a tree. A factor associated with the accident was the tree."





NBC AMD Observations


Delta Junction, AK July 28, 2005

The RIGHT STUFF

Discussion

- Good Communication Procedures
- Installed Experimental Remote Camera for real time weather
- Excellent Base Operations support





NBC AMD Observations


Delta Junction, AK July 28, 2005

Corrective Actions/Options

Discussion

- Do not allow operations to continue after a blade strike is known or suspected to have occurred
- Train new crews in LZ clearing and safety procedures
- Remote fuel sites should be monitored and maintained properly





Coldfoot, AK

August 20, 2005

Piper PA-18

Mission

Law Enforcement

Damage

Substantial

Injuries

N/A


Procurement

Fleet

NTSB ID

ANC05TA126





Coldfoot, AK

August 20, 2005


Issues

More complete
aerial recon of
remote landing
sites

Develop a back-up
plan prior to
landing

Plan the flight, fly
the plan (avoid
last second
changes)





Coldfoot, AK

August 20, 2005

After landing to a remote "bush" airstrip the pilot attempted to taxi to the side to clear the strip.


During the taxi the left main landing gear hit a rut and the aircraft tipped forward on to its nose.

The pilot was not injured, but the aircraft received substantial damage to the firewall and forward fuselage.



Engine deflected to the right
and damage to propeller blades




A photograph of an engine compartment, likely from a small aircraft. On the left is a red and white striped fairing. The engine is visible with a yellow valve cover and red corrugated hoses. A yellow oval highlights a dark, damaged area on the firewall. A text box with yellow text on a black background points to this area.

Damage to
firewall







NTSB Probable Cause ***Coldfoot AK, August 20, 2005***



The National Transportation Safety Board


The National Transportation Safety Board determined that the probable cause of this accident was ...

Probable Cause

"The pilot's selection of unsuitable terrain for landing, which resulted in the airplane nosing down during the landing roll.

A factor associated with the accident was the rough and uneven terrain."





NBC AMD Observations


Coldfoot, AK July 20, 2005

Corrective Actions/Options

Discussion

- Conduct your aerial recons as though your life depends on it
- Have a primary plan... and a back-up plan (a way out)
- Avoid spontaneously changing your plan





Elko, NV
August 23, 2005

PZL M-18T
Turbine
Dromader

Mission

Fire Suppression

Damage

Substantial

Injuries

Minor

Procurement

Call When
Needed

NTSB ID

LAX05TA277





Elko, NV
August 23, 2005

Issues


Unnecessary risk
taking

Be alert to
changing weather
conditions -
especially heavy
winds

Communications

Don't hesitate to
turn down a
mission when
appropriate





Elko, NV

August 23, 2005

After performing a retardant drop under downhill and downwind conditions the aircraft was unable to establish an adequate rate-of-climb to prevent ground impact.

The pilot elected to make an emergency off-airport landing under control rather than attempt to fly out.

The pilot received minor injuries.











Point of initial impact



Heading 054°





NBC AMD Observations


Elko, NV, August 23, 2005

The RIGHT STUFF

Issues

- Mishap reporting and response coordination was excellent
- ✓ Proper notification to AM and Bureau National Office
- ✓ Medical evacuation of pilot
- ✓ Wreckage preservation





AM Observations

Elko, NV, August 23, 2005

Corrective Actions/Options



Issues

- Weather recognition
 - ✓ Be alert to changing weather conditions - especially heavy winds
- Keep lines of communication open
- Doing "dry runs" is an acceptable practice
- I am not going back out there because..."




DOI FY 05 Aviation Mishaps



Discussion





DOI FY 05 Aviation Mishaps



Ideas for Managing Risk

Avoid taking unnecessary risks

Medium risk syndrome

Project Aviation Plans

Pre-mission briefings


Pre-use inspections

Mitigate known risks

Document remaining hazards

Have an escape plan

Turn-down protocol



DOI FY 05 Aviation Mishaps



Lessons learned (again)

Use checklists

Don't fly in a damaged aircraft

Timely mishap reporting and SAFECOMs

Crew Resource Management

(speak up, and shut up, when appropriate)

Aviation Life Support Equipment

(take care of it and it will take care of you)